

BRISTOL INTERNATIONAL AIRPORT (BRS/EGGD) – MARCH 2018 MOVEMENTS

1. D-IMGW Ce525A (AHO973K, dep't 3rd, AHO834M), G-EZPS A320 (Resident with easyJet, replaced G-UZHB), G-EZWR A320 (Resident with easyJet, replaced G-EZUH), G-OOBB B757 (TOM9001, ex HEL, resident with TUI, replaced G-CPEU), G-PRPN DHC8 (BEE485Y, dep't 3rd, BEE0441, Exeter diversion).
2. D-ASTT A319 (GMI3597, dep't 3rd, GMI716), G-CISK RJ145 (EZE057P, positioned in ex SOU), G-CKAF RJ145 (BMR9251, positioned in ex LGG), G-CPEU B757 (TOM9865, ex LTN, resident with TUI, replaced G-OOBB, dep't as TOM9011), G-FDZD B737 (TOM9012, dep't 3rd, TOM90B).
3. G-CISK RJ145 (EZE065P, dep't to LGW, returned 5th, EZE2765), G-CKAF RJ145 (BMR9261, dep't to CWL, returned later as BMR9263), G-CPAS EC135 (UKP01, operated NE of RW27, 1325hrs), G-EMBN RJ145 (BMR9461, dep't to FAB, returned 4th, BMR9471), G-EZRD A320 (EZY19PZ/85WM), G-EZTB A320 (EZY98ZV/21VR), G-FBEN EMB195 (BEE874J, dep't 4th, BEE044Z, Exeter diversion), G-FDZD B737 (TOM72Y/9031), G-ISLL ATR72 (BCI716/7), G-PULA Falcon 2000 (CLF698), G-OOBB B757 (TOM9016, ex MAN, based with TUI), OY-NDP Ce525A (Reg/CLF5T, (n/s)).
4. EI-EVA B737 (Resident with Ryanair, replaced EI-EFY), G-EZDL A319 (EZY9008, ex STN, based with easyJet, replaced G-EZEY, dep't to EDI, EZY9015), G-EZRD A320 (EZY19PZ/49DV), G-EZRK A320 (Resident with easyJet, replaced OE-IJD), G-EZOI A320 (EZY79VN/568), G-EZUJ A320 (EZY85BA/431), G-EZWP A320 (EZY98ZV/21VR), M-OTOR Be200 (EZE08A/B), N542MP Hondajet, OE-LKJ A319 (EZY82XB/46HF), OE-LQX A319 (EZY82LH/35BD/31XG/14KJ), OY-NDP Ce525A (n/s), SP-ENP B737 (ENT642/590P), 9H-JOY CL850 (AXY417, dep't 5th, AXY502).
5. EI-FZR B737 (Resident with Ryanair, replaced EI-EVA), G-CPEU B757 (TOM9047, dep't to LGW), G-EZRP A320 (1st visit with easyJet, resident, replaced G-EZPS), G-RJXG RJ145 (BMR9111, ex BHX, based with BMA, replaced G-CKAF), HA-LXM A321 (1st visit with Wizz), OE-LQX A320 (EZY82LH/35WU), OY-NDP Ce525A, G-ZAPX B757 (AWC891/2). Resident easyJet A319's: G-EZAL/AX/DK/DL/FY/IX. A320: G-EZRI/RK/RP/UF/WR, OE-IJI/IVD.
6. G-CKAG RJ145 (Resident with BMA, replaced G-EMBJ), G-EZPO A320 (EZY85BA/431), G-EZDK A319 (EZY9003, positioned in ex CWL), G-EZWP A320 (EZY98ZV/21VR), G-RJXF RJ145 (BMR9123, positioned in ex ABZ), G-RJXGRJ145 (BMR9221, positioned in ex CWL), G-RJXI RJ145 (Resident with BMA, replaced G-RJXB), OE-GPS Ce550 (TYW846S, (n/s)).
7. EI-EPF B737 (Resident with Ryanair, replaced EI-FZR), EI-GJB B737 (1st visit with Ryanair), G-EZPT A320 (Resident with easyJet, replaced G-EZWR), G-EZTB A320 (EZY98ZV/21VR), G-EMBI RJ145 (Resident with BMA, replaced G-RJXF), G-OOBB B757 (Resident with TUI, replaced G-OOBH), G-RJXH RJ145 (Resident with BMA, replaced G-RJXL), OE-LKE A319 (EZY85BA/431, 1st visit with easyJet Europe).
8. G-OOBB B757 (Resident with TUI, replaced G-OOBB), G-RJXH RJ145 (BMR9141, dep't to BHX, returned 12th, BMR931P), OE-LQG A319 (EZY31XG/14KJ, 1st visit with easyJet Europe), OE-LQK A319 (EZY79VN/568).
9. D-CEFD Ce525B (EFD3C, (n/s)), G-EZTB A320 (EZY98ZV/21VR), G-EZUJ A320 (EZY85BA/431), G-FDZW B737 (TOM80W, dep't 10th, TOM90B), G-POWH B757 (AWC681Y, dep't 10th, AWC811), G-CJDB Ce525 (n/s), M-ICRO Ce525C (EZE08B/C), OE-LQG A319 (EZY82LH/35BD/31XG/14KJ), OE-LQX A319 (EZY79VN/568), OE-LQZ A319 (EZY91XH/26NC), SP-ENP B737 (ENT502P, dep't 10th, ENT629).
10. CS-DKH Gulf 550 (NJE321G/8FR), EI-GJE B737 (1st visit with Ryanair), EI-GJF B737 (1st visit with Ryanair), G-CJDB Ce525, G-EZRD A320 (EZY19PZ/85WM), G-EZWP A320 (EZY98ZV/21VR), G-FDZW B737 (TOM72Y, dep't 11th, TOM3XY), G-RJXG RJ145 (BMR9461, dep't to LPL, returned later, BMR9463).
11. CS-PHK Phenom 300 (NJE2CP/441N), EI-EVR B737 (Resident with Ryanair, replaced EI-EPF), G-BYAY B757 (Resident with TUI, replaced G-OOBD), G-EZOW A320 (Resident with easyJet, replaced OE-IVD), G-EZRH A320 (EZY85BA/431), G-EZWP A320 (EZY98ZV/21VR), G-KLNH A109SP (SXN10), G-RJXP RJ135 (Resident with BMA, replaced G-RJXK), OE-LKE A319 (EZY82XB/46HF), OE-LQW A319 (EZY79VN/568), OE-LQX A319 (EZY82LH/35BD/31XG/14KJ), SP-ENP B737 (ENT642/521P).
12. CS-CHA CL350 (NJE5KZ, Staverton diversion), G-CKAF RJ145 (BMR9112, ex CDG, based with BMA, replaced G-EMBI), G-PULA Falcon 2000 (CLF193), G-RJXL RJ135 (Resident with BMA, replaced G-RJXI), G-YEDC Ce525B (EDC550), OE-LQW A319 (EZY82LH/35WU/31XG/14KJ). Resident easyJet A319's: G-EZAL/AX/BO/DL/FY/IX. A320: G-EZOW/PT/RI/RK/RP/UF/OE-IJI.
13. EI-EVS B737 (Resident with Ryanair, replaced EI-EPC), EI-GDZ B737 (1st visit with Ryanair), EI-EMH B737 (RYR912/3), G-EZUJ A320 (EZY85BA/431), G-EZWP A320 (EZY98ZV/21VR), G-FLYW Be200 (PYN01/CLF4T, (n/s)), G-NIAB Be200 (CWY999A/B), G-RJXC RJ145 (Resident with BMA, replaced G-RJXP), G-RJXI RJ145 (Resident with BMA, replaced G-CKAF), G-OOBB B757 (Resident with TUI, replaced G-BYAY), PH-EXU EMB1775 (1st visit with KLM).
14. G-EMBJ RJ145 (Resident with BMA, replaced G-EMBN), G-EZWP A320 (EZY98ZV/21VR), G-FLYW Be200 (CLF4T/PYN01), G-DMPI A109E (Jockey99, overflown NE-SW, 1722hrs), G-VPPL TB20, OE-LKE A319 (EZY85BA/431).
15. EI-EVR B737 (RYR912/3), G-EZTB A320 (EZY9004/79YF/98AT/9005), G-EZTZ A320 (Resident with easyJet, replaced G-EZUF), G-FLYW Be200 (PYN01/CLF4T, (n/s)), G-IASM Be200 (BRO67P, dep't 16th, CLF5T), G-RJXH RJ145 (BMR9001, dep't to CWL, returned later, BMR9001), G-RJXR RJ145 (Resident with BMA, replaced G-RJXC), G-UJET Learjet 45 (EGL1120), G-VPPL TB20, LX-RSQ Learjet 45 (DUK5AMB), OE-LKM A319 (Resident with easyJet, replaced G-EZBD, 1st visit with easyJet Europe), OE-LQW A319 (EZY79VN/568).
16. CS-DUC BAe125 (NJE3ER/662C, Staverton diversion), D-CEIS Ce680 (EFD6S), EI-EVR B737 (RYR912/3), G-CHMR RJ145 (EZE051P, positioned in ex BOH), G-CKAG RJ145 (BMR9151, positioned in ex FRA), G-EMBI RJ145 (Resident with BMA, replaced G-EMBJ), G-EZTA A320 (Resident with easyJet, replaced G-EZTZI), G-EZWP A320 (EZY98ZV/21VR), G-EZWT A320 (Resident with easyJet, replaced G-EZRI), G-FLYW Be200 (CLF4T/PYN01), G-CISK RJ145 (EZE052P, positioned in ex LPL), G-FDZW B737 (TOM80W, dep't 17th, TOM90B), G-IASM Be200 (CLF5T, (n/s)), G-NIAA Be200 (CWY999A/B), G-POWH B757 (AWC812/681W), EO-FPP Ce510 (GAC331P/220Q), OE-LQZ A319 (EZY91XH/26NC), SP-ENP B737 (ENT560P, dep't 17th, ENT629), 9H-GTC B737 (HAT4902, dep't 18th, HAT4801).
17. G-CKAF RJ145 (BMR9361, ex BRU, based with BMA, replaced G-CKAG), G-EZWP A320 (EZY98ZV/21VR), G-FDZW B737 (TOM72Y, dep't 19th, TOM3XY), G-IASM Be200 (CLF5T, dep't 23rd, BRO32P), G-PULA Falcon 2000 (CLF700), G-RJXE RJ145 (BMR9161, positioned in ex ABZ), G-OOBP B757 (TOM9852, ex LTN, based with TUI, replaced G-OOBB), N1962J Ce750 (Dep't 19th), OE-IVU A320 (EZY19PZ/85WM).
18. D-CSCA Ce525B (SCR378), EI-GDM B737 (Resident with Ryanair, replaced EI-DAR), G-CKAF RJ145 (BMR9371, positioned out to BRU), G-OOBB B757 (TOM9080, dep't to GLA), LX-ONE Learjet 45 (DUK1AMB, (n/s)), OE-FHK Ce510 (GAC9166, dep't 19th, GAC730A), SP-ENP B737 (ENT642/501P).
19. D-ISUN Ce525A (ECA5C), EI-GDX B737 (1st visit with Ryanair, resident, replaced EI-EMH), G-EZFW A319 (EZY9015, ex LTN, resident with easyJet), G-FLYW Be200 (PYN01), G-RJXP RJ135 (Resident with BMA, replaced G-RJXG), G-TCDZ A321 (TCX4804/95VT/27XL/4805), M-CDBM Be200 (VSB2, 1st visit on Vickers BEF shuttle), PH-ANO Ce560XLS. Resident easyJet A319's: G-EZAL/AX/BH/FW/GF/IM/OE-LKM, A320: G-EZOW/PT/RI/RK/RP/TA/WT/OE-IJI.
20. CS-DXH Ce560XLS (NJE8FR, dep't 21st, NJE207Y), D-CPMI Ce560XLS, G-EMBI RJ145 (BMR9123, positioned in ex LYS), G-EZGF A319 (EZY9004, dep't to LTN), G-EZTB A320 (EZY9013/14QC/26LE/9014), G-EZUJ A320 (EZY85BA/431), G-FSEU Be200 (BRO31P/CLF4T, dep't 23rd, BRO31P), G-RJXB RJ145 (Resident with BMA, replaced G-RJXI), G-RJXR RJ145 (BMR9721, dep't to LIS), G-RVSA RV6A.
21. G-BNKD Ce172N (New resident with Bristol Flying), G-EZWP A320 (EZY85BA/431), G-RJXA RJ145 (BMR9331, ex GOT, based with BMA), N321MM Be90, OE-FWF Ce510 (GAC008N/520U), OE-LKG A319 (EZY85BA/431, 1st visit with easyJet Europe).

RZR1EE/6LB	EI-			EPC				EPC		EPC		EMH			EPC		EMH
RZR1WL/6TF	EI-	EMH		EMH	DYX			DLF	EPC	EMH		EPF	DWV		DHP	EVR	EVS
RZR2WC/10BB	EI-			FOT	EMP	EVH		EMP	FZR	EMP		FZC	EFI	EVP	EBL		EVS
RZR3CA/8262	EI-		EVH	DAR	*	EMH		EMH	EPF	EPF			*	EPC	EMH		EVS
RZR3DL/159G	EI-	DAR		DAR	FRP	*		EPC	GJB	DLI		GJF	DLB	GJB	GDZ	ENM	FZW
RZR3RA/46ZD	EI-			DAR	DAR	EMH		ENJ	EPF				EPF	EPC		ENG	
RZR5UM/41LK	EI-			DAR	FRP	EMH		DYN	EPF					EPC		GDB	
RZR6AG/89GG	EI-			DAR	FRP	EMH		EMH	FRW	EMH				EPC			
RZR6NK/6PC	EI-			DAR	FRP	EMH		EMH	EPF					EPC			
RZR6QZ/3775	EI-			DAR	FRP	EMH		EMH	EPF					EPC			
RZR6WD/52DP	EI-			DAR	FRP	EMH		EMH	EPF					EPC			
RZR7AX/7FR	EI-			DAR	FRP	EMH		EMH	EPF					EPC			
RZR7VG/60QR	EI-	FRB		EPC	EPC	EMH		EMH	EPF			DAR		EMH	EMH	EMH	EVS
RZR8PM/88GE	EI-	ENW		FRZ	EPC	EMH		EMH	EPF			GJE		DAH	EMH	DAF	GDM
RZR9MX/44RG	EI-	EPC			EFT	EMH		EMH	FZM	DLI		FZM		EMH	FRZ	EVR	EKT
RZR9TD/93VU	EI-	EKB	DHD		EVG	EMH		EMH	DCZ	ENO			EPC	DAM			DAM
					EPC	EPC		EMH		EMH			EMH	EMH			EVS
RZR18MF/86YB	EI-			EFY	EPC	EPC		EMH		EMH			EMH	EMH			EVS
RZR19UZ/25AM	EI-				EPC	EPC		*		EMH			EMH	EMH			EVS
RZR21LD/8262	EI-				FZR	FZR				EPC				EVR			EVR
RZR34MU/96JV	EI-				EMH	EGA				DCM			EPC	EVR			EVR
RZR51VE/89NN	EI-			DAR	DPD	DAR		FZR		EPC			FOC	DYO	EVR		EVR
RZR82MG/8254	EI-									EPC				EVR			EVR
RZR4753/4754	EI-									EPF							EVR

Movement Information is kindly supplied by Phil Claridge, Harry Pitchers and Paul Hobden.

THIS INFORMATION IS ONLY FOR USE ON WWW.EGGD.CO.UK UNLESS PRIOR PERMISSION FOR PUBLICATION HAS BEEN SOUGHT

Gary Morris (www.eggd.co.uk) 2018
E. & O.E